WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

April 1, 2010

_	_	$\overline{}$		
		ı	٠	
	. •	.,		

Internal File

THRU:

FROM:

RE:

Steve Christensen, Environmental Scientist Skappen 2009 3rd Quarter Water Monitary Mine, C/007/0010 2009 3rd Quarter Water Monitoring, Canyon Fuel Company, Soldier Canyon

The approved water-monitoring plan can be found in Section 7.31.2 and summarized in Tables 7.31-1 through 7.31-4 of the Mining and Reclamation Plan (MRP). The narrative and tables identify the monitoring that is currently required as well as the monitoring requirements that will be required if the mining activity resumes at the site.

The Soldier Canyon Mine has been in temporary cessation since 1998. Due to the lack of coal mining activity at the site and the amount of water quality data previously obtained during active operations at the site, several water-monitoring sites have been discontinued. (See Discussion Below)

1. Was data submitted for all of the MRP required sites?

YES 🖂

NO \square

. Springs -

Table 7.31-1, Recommended Monitoring Program Soldier Canyon Mine, identifies six springs. Of the six springs, four of them (5, 10, 23 and 24) have been identified, as springs where monitoring activity will resume if and when the mine becomes active. The remaining two springs (4 and 8) have been discontinued from active monitoring for the Soldier Canyon Mine. However, the springs are still monitored as part of the Dugout Canyon water-monitoring plan.

During temporary cessation, the Permittee is **not required** to monitor any springs at the Soldier Canyon Mine.

Streams -

A total of seven surface water-monitoring sites are listed in Table 7.31-1, Recommended Monitoring Program Soldier Canyon Mine. Of the seven, two are actively monitored (G-5 and G-6). Three of the stream sites (G-2, G-8 and G-9) have been discontinued. The approved MRP detailed how monitoring of these sites would end one year following the end of mining activity in the area. Monitoring of spring G-10 will resume in the quarter the Soldier Canyon mine portals are reopened for active mining. Spring G-7 will be sampled during the first wet year and first dry year in order to enable the preparation of base-flow hydrographs.

During temporary cessation, the Permittee is required to sample G-5, and G-6 flow, and the laboratory parameters outlined in Table 7.31-4 each quarter. Several analytical parameters are only sampled during the 3rd quarter (dissolved iron, total iron, dissolved manganese and total manganese).

The Permittee monitored and reported the data as required for G-5 and G-6.

Wells-

Groundwater monitoring wells MW-1M, MW-1C, MW-2M and MW-3M have been discontinued. Approximately 4.5 years of baseline data were collected from these wells in the area of the refuse pile. No significant impacts were noted during that time and due to the breadth of baseline data obtained from these wells, a thorough characterization of the groundwater system in this area has been documented.

The monitoring of wells 5-1, 6-1 has been discontinued. Monitoring well 10-2 is no longer monitored as part of the Soldier Canyon MRP, but is monitored as part of the adjacent Dugout Canyon MRP. Monitoring well 32-1 is currently not monitored, however monitoring of this site will resume if and when the mine becomes active.

During temporary cessation, the Permittee is **not required** to sample any wells at the Soldier Canyon Mine.

UPDES-

The Soldier Canyon Mine contains three active UPDES sites. They are: MW-1 (001) mine water discharge, MW-2 (003) mine water discharge and UT0023680-002 sediment pond discharge. The Permittee is required to monitor each UPDES site monthly. However, none of the three UPDES sites has produced any measurable flow in some time. MW-1 (001) last produced a discharge on December 13th, 1991. MW-2 (003) last flowed on March 16th, 1998. UT0023680-002 last flowed on October 1st, 1985.

None of the three UPDES sites recorded any flow during the quarter.

2.	Were all required	parameters repor	ted for each site?	YES	\boxtimes	NO 🗌
----	-------------------	------------------	--------------------	-----	-------------	------

3. Were any irregularities found in the data?

YES	\boxtimes	NO [
1110	ν \sim	110

Dissolved Magnesium (D-Mg) and Carbonate (Carb) were reported outside of two standard deviations from the mean for surface water monitoring site G-5. Based upon the data, the increases in D-Mg and Carb that were reported this quarter appear to follow seasonal trends. It's likely that the higher D-Mg and Carb concentrations correspond to the seasonal increase in frequency and intensity of rainfall events during this time of the year. (See Charts Below).

TDS values for both G-5 and G-6 continue to trend well below the 3,000-mg/L value as established by Rule R317-2 Standards of Quality for Waters of the State. For this quarter, G-5 and G-6 produced TDS levels of 700 mg/L and 510 mg/L respectively

4. On what date does the MRP require a five-year re-sampling of baseline water data.

The MRP does not contain a commitment for re-sampling of baseline water data.

5. Based on your review, what further actions, if any, do you recommend?

The Permittee should review their sample collection methods in order to try and identify areas where contamination may be introduced. In addition, the Permittee should consult with the laboratory and try to identify what may be producing the questionable reliability values.

Continue to monitor trends in TDS and it's components.

O:\007018.SOL\Water Quality\WQ09-3.doc







